	Property is: Single Fam	nily 🗹	Duplex	□ Other □		
Date:	10/19/2016					
					the Redevelopment Authority, and their rep	
	onsibility for problems discovered and by private lenders, insurance cor				gh error or oversight. The list does not nece E programs.	ssarily include
Exterior (	Condition Report					
Location Site	Required Work Landscaping	n/a ✓	Yes 🗌	Note/Comments Self Help	\$	Cost
	Steps/Handrails	n/a ☑	Yes 🗌		\$	
	Service walks	n/a _	Yes 🗸		\$	2,500.00
	Fencing	n/a ☑	Yes 🗌		\$	
	Parking	n/a ☑	Yes 🗌		\$	
	Retaining walls	n/a ☑	Yes 🗌		\$	
	Other	n/a 🔲	Yes 🗌		\$	
	Other	n/a 🗌	Yes 🗌		\$	
Garage	Singles: repair	n/a 🗌	Yes 🗌		\$	
	Shingles: Roof over existing	n/a $\square$	Yes 🗌		\$	
	Shingles:Tear off & re-roof	n/a 🗌	Yes 🗌		\$	
	Gutters/downspouts	n/a 🗌	Yes		\$	
	Flashing	n/a 🗌	Yes 🗌		\$	
	Eaves	n/a 🗌	Yes 🗌		\$	
	Siding	n/a 🗌	Yes 🗌		\$	
	Doors	n/a 🔲	Yes 🗌		\$	
	Windows	n/a 🔲	Yes 🗌		\$	
	Slab	n/a 🗌	Yes 🗸		\$	2,200.00
	Paint	n/a 🗌	Yes 🗌		\$	
	Electrical	n/a 🗌	Yes 🗌		\$	
	Other	n/a 🗌	Yes 🗌		\$	
Porches	Roof	n/a 🗸	Yes 🗌		\$	
	Deck-upper	n/a 🔽	Yes		\$	
	Decklower	n/a 🔽	Yes 🗌		\$	
	Steps/handrails	n/a _	Yes 🗸	stairs and rails	\$	700.00
	Ceiling	n/a 🔽	Yes 🗌	_	\$	
	Guardrails	n/a 🔽	Yes 🗌	_	\$	
	Structural	n/a 🗌	Yes 🗸	repair south column	\$	1,000.00
	Paint	n/a 🗌	Yes 🗸		\$	450.00

n/a Yes

\$

Other

## House

Chimney	n/a 🗸 Yes 🗌	\$ 
Shingles: repair	n/a 🗹 Yes 🗌	\$ 
Shingles: Roof over existing	n/a 🗹 Yes 🗌	\$ 
Shingles:Tear off & re-roof	n/a 🗹 Yes 🗌	\$ 
Gutters/downspouts	n/a 🗹 Yes 🗌	\$ 
Flashing	n/a ☑ Yes □	\$ 
Eaves	n/a 🔽 Yes 🗌	\$ 
Siding	n/a Yes 🔽	\$ 6,000.00
Storm Doors	n/a 🗹 Yes 🗌	\$ 
Prime ("main") Doors	n/a 🗹 Yes 🗌	\$ 
Storm Windows	n/a 🗹 Yes 🗌	\$ 
Prime ("main") Windows	n/a ☑ Yes □	\$ 
Paint	n/a  Yes  foundation and trim	\$ 1,500.00
Foundation	n/a Yes 🗸 tuck pointing	\$ 500.00
Electrical	n/a 🗹 Yes 🗌	\$ 
Other	n/a 🗌 Yes 🗌	\$ 
Other	n/a  Yes	\$ 
Other	n/a 🗌 Yes 🗌	\$ 
Other	n/a Yes	\$

Exterior: Estimated Cost:\* \$ 14,850.00

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ondition Report								
	Unit: Entire unit (single family)	7				Lower unit of duplex			
Mechanical Heating	Upper unit of duplex Required Work	Ш				Other	Ш		
-	Repair/replace boiler	n/a	<b>V</b>	Yes		_		\$	
	Repair radiation	n/a	<b>V</b>	Yes		_		\$	
	Repair/replace furnace	n/a		Yes	<b>V</b>			\$	3,300.00
	Repair ductwork	n/a		Yes	<b>V</b>			\$	500.00
	Replace thermostat	n/a	<b>V</b>	Yes				\$	
	Repair/replace grilles	n/a	<b>V</b>	Yes		_		\$	
Electrical	Tune boiler/furn. insp ht exchange	n/a	7	Yes		_		\$	
Liectrical	Repair/replace receptacles	n/a		Yes	<b>V</b>	_		\$	500.00
	Repair/replace switches	n/a		Yes	1			\$	500.00
	Repair/replace fixtures	n/a		Yes	1	_		\$	1,000.00
	Install outlets and circuits	n/a		Yes	<b>4</b>	_		\$	1,000.00
	Install outlets and circuits	n/a	<b>V</b>	Yes				\$	
	Install outlets and circuits	n/a	<b>y</b>	Yes		_		\$	
	Install outlets and circuits	n/a	<b>V</b>	Yes		_		\$	
	Upgrade service	n/a		Yes	1			\$	2,000.00
	Other	n/a		Yes		<del></del>		\$	
	Other	n/a		Yes		_		\$	
Plumbing	Repair/replace kitchen sink	n/a		Yes				\$	
	Repair/replace kitchen sink fauce	n/a		Yes		_		\$	
	Repair/replace tub	n/a		Yes		=		\$	
	Repair/replace tub faucet	n/a		Yes				\$	
	Repair/replace toilet	n/a		Yes				\$	
	Repair/replace lavatory	n/a		Yes				\$	
	Repair/replace lavatory faucet	n/a		Yes				\$	
	Repair/replace wash tub	n/a		Yes				\$	
	Repair/replace wash tub faucet	n/a		Yes		_		\$	
	Unclog piping:	n/a		Yes		_		\$	
	Repair drain/waste/vent piping	n/a		Yes	1			\$	2,000.00
	Repair water piping	n/a		Yes	1	_		\$	2,000.00
	Repair/replace water heater	n/a		Yes	<b>V</b>			\$	750.00
	Other	n/a		Yes	<b>V</b>	complete kitchen		\$	1,500.00

n/a Yes complete bathrooms

Other

\$

3,200.00

Windows							
	Replace broken glass	n/a		Yes	1	7	\$ 
	Repair or replace sash	n/a	1	Yes			\$
Doors	Repair or replace doors	n/a	<b>√</b>	Yes			\$
	Repair or repl. locks/latches	n/a	<b>4</b>	Yes		Self Help	\$
Walls/Ceiling	~						
	Repair or repl. @ defective	n/a		Yes	1		\$ 2,500.00
Paint	Repair or repl. @ defective	n/a _		Yes	<b>7</b>		\$ 500.00
Fire Safety							
•	Install smoke/CO alarm:bsmt.	n/a		Yes	<b>V</b>	Self Help	\$ 50.00
	Install smoke/CO alarm: 1st flr.	n/a		Yes	<b>V</b>	Self Help	\$ 50.00
	Install smoke/CO alarm: 2nd flr.	n/a		Yes	1	Self Help	\$ 50.00
Handrails	Repair/replace defective	n/a		Yes	7	Self Help	\$ 200.00
Stairs	Repair defective	n/a	<b>7</b>	Yes			\$
Floors	Repair defective	n/a		Yes	7	through out	\$ 2,500.00
Other							
		n/a		Yes			\$
		n/a		Yes			\$
		n/a		Yes			\$ 
		n/a		Yes			\$
						Interior: Estimated Cost:	\$ 24,100.00
						Total Exterior and Interior Cost:*	\$ 38,950.00

Inspected by: Andy Yeager Date: 10/20/16

## **Self Help**

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

## **Important Information Regarding Permits**

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.

<sup>\*</sup>average contracted cost. Actual costs may vary. Self help will reduce the amount.